

Brass 1-1/2" x 1-1/2" or 1-1/2" x 1-1/4" P-Trap with hi-box flange (D400-1), 2 ea. - 1/2 IPS x 3/8 OD comp. angle stops (D105), 2 ea. - 1/2" IPS sure grip flanges (D129), 2 ea. - 3/8" x 20" corrugated washer (D114).

Thread on washers

